



Baby Lock Flourish II (Model BLMFO2) Software Update Version 1.30

November 2021

Introduction

If the software version of your Flourish II (Model BLMFO2) is earlier than version 1.30, an update program is now available for download to improve its performance.

Version 1.30 update will provide the following changes:

1. The optional magnetic frame EMF180 can be recognized on the machine.

To confirm the software version of your BLMFO2

2. Press the power switch to "|" to turn on your machine.
3. Press  (Settings key) to display the machine's settings screen.
4. Switch the settings screens by using ◀ (Previous page key) or ▶ (Next page key) to display the machine's program version.



5. If the "Version" shown in the screen is already "1.30" or later, it is not necessary to update your machine with this software version.



How to update your machine's software


You can use a **formatted** USB Flash drive to update your machine's software.

***** NOTE *****


- Do not turn off your machine while the machine is saving the update software to itself. If the machine's power is turned off while saving the update software, it may result in damage to the machine.
- Use a 4GB to 8 GB USB flash drive when updating the machine.
- Check that no data except for the update file (FEMTE1A130.upf) is saved on the formatted USB Flash drive, before beginning update.

1. Insert the USB Flash drive into the USB port on the computer.
2. Copy only the update file, , to the USB Flash drive.
3. Safely remove the USB Flash drive from the USB port on the computer.


4. With the machine off, press and hold  “Presser Foot Lifter Button” while turning the main power on.




5. The following screen will appear on the LCD.




6. Insert the USB flash drive into the USB port on the machine.



7. Touch  (LOAD key).



8. The following screen appears on the LCD. Do not turn off your machine while the machine is saving the update software to itself.



9. When the following screen appears, updating is completed.



10. Remove the USB flash drive and turn the machine off and on again.
11. The machine's software has been updated to version 1.30.



Baby Lock Flourish II (BLMFO2) Update History

Version 1.26 update will provide the following changes:

1. Periodic software update, does not affect consumer features

Version 1.22 update will provide the following changes:

1. Minor improvement to touch panel function.

Version 1.21 update will provide the following changes:

1. Revised the wording of messages.