



## **ProStitcher Premium Update History**

### **Version 19.04.0501 (Released April 2019)**

#### **Release Notes**

- Opti-Stitch™ is a feature which automatically calculates speed and acceleration to match the quilter's chosen design and responds with optimal stitch performance. Pro-Stitcher Premium will smoothly slow down and speed up in and out of corners. Designs will be executed with improved accuracy, even with the most intricate patterns.
- Manual control of speed and acceleration are available within the program so quilters can modify performance if necessary
- Baste stitch button
- Motors not locked at end of pattern (can change in settings)
- Design Points view
- Simulation license is no longer required
- Some user interface icons have been updated
- Functional tack stitch

### **Version 18.11.0461 (Released November 2018)**

#### **Release Notes**

- Supports Art and Stitch 5
- Eliminates long stitch after tie-off on Regalia

### **Version 18.08.457 (released October 2018)**

**Release Notes:** SA5-271-78M8 (Acer Switch Alpha 12 i7) added to Master Machine Names list

### **Version 18.05.0455 (released July 2018)**

**Release Notes:** Restored Machine Update icon on Regalia console

### **Version 18.05.0454 (released June 2018)**

#### **Release Notes**

- Tablet temperature reduction (further reduces CPU usage)
- Eliminates long stitch during tie-off
- Simulation button no longer disappears

- Modify selection (Transform to Select wouldn't update screen to show)
- Updated text in Help
- Fixed two minor crop bugs
- Image thumbnail improvements
- Thread break sensor removed for non-compatible machine types
- Logging crash fixed

## **Version 18.02.0451 (released April 2018)**

### **Release Notes**

- Changes Original Height and Original Width to Original H and Original W so it fits in the icon boxes
- Reset works for flip and mirror
- Improved crop so it no longer disconnects merged jump points
- Closing PS Standard and running PS Premium works without reboot or reinstall. However, closing PS Premium and running PS Standard does not work.
- Basting stitches added for compatible Crown Jewel machines
- Default maximum motor speed set for 2200 instead of 1800 for Crown Jewel III machines
- Max tie-off distance is .25
- Regalia Tension Reset button has warning/instruction “Are you sure you want to reset tension?” and refers customer to user manual
- Baseline no longer closes the selected window pane on the right side of the screen
- Console has tray icon so user can exit/view logs (must right click on tray icon to access)
- Installer removes HQF files in the Baby Lock Designs folders and replaces them with HQV files. Triangles HQF files have not been completed yet so they will continue to be a mix of HQF and HQV.
- PS Icon on OSKStarter bar no longer launches the PS Premium program if it is already open. If open, it correctly toggles between desktop screen and Pro-Stitcher Premium screen. If not already open, it will launch.
- Updater will always install the machine console icons
- Updater will always install desktop shortcut
- SW312-31 (Acer Switch 3) added to Master Machine Names list
- User will be prompted if Pre-Install needs to be run

## **Version 18.02.0447 (released February 2018)**

### **Release Notes:**

- Prevents jump lines from being stitched out
- User can no longer change design selection during pause
- Fixed a bug where a bad design would prevent other designs from working
- Improves stability of HQV file loading
- Turns off location polling when the user presses the Run button, which reduces likelihood of losing communication during stitching
- Reduces CPU usage, which potentially reduces tablet temperature and reduces likelihood of losing communication between machine and PS tablet
- Sidebar no longer is hidden after selecting Baseline after a modification

- Can select Basting stitches for Crown Jewel and Coronet versions with hardware support
- Improves communications between Regalia machines and the PSP program
- Reduces likelihood of unwanted tie-offs
- Resizing a multi-point area works correctly
- Simulator does not require Designs Folder on computer to load correctly
- Preinstall v10 included

#### **Version 17.11.0441 (released November 2017)**

##### **Release Notes**

- Reposition Zero works correctly
- Simulation crosshairs are green and icon updated
- Corrected max speeds
- No longer shows "NAN" in rotation
- Clearing the Area also clears the trace
- New Diagrams for threading
- Reposition current works, if you reposition start it clears current
- New Start/End working correctly
- BL Regalia machine option added
- Channel locks enabled during stitch out
- Improved Area Resize behavior
- Changed motor icon for Simulation
- Simulator no longer requires FTDI and motor DLLs to be installed
- Fixed slow stitch-out for levered carriages
- Fixed "multiple application has stopped working" crashes
- Numeric fields now allow a decimal point

#### **Version 17.09.0433 (released October 2017)**

##### **Release Notes**

- New Feature: Audible beep is heard when Area or Mark points are set
- New Feature: Rubberband Area
- New: Red crosshairs when in Simulation Mode
- Default torque limit is now set to 100 and reverts to default if invalid limit entered
- Improves calculator stability
- Simulation license button available on Alpha 12 tablets
- Channel lock buttons disabled during stitch out
- Half/full stitch enabled during pause
- Ability to set Auto Jump to 0
- Improved simulator for non-English operating computers
- Duplicated or copied designs/groups retain name and are numbered to differentiate
- Improves digital design file quality for some Baby Lock designs

## **Version 17.02.0416 (released February 2017)**

### **Release Notes**

- Improves software stability and decreases frozen screens and program crashes
- Improves new/auto start point functionalities
- Restores proper functionality of Resume after Drag and Drop
- Restores stitch ability between two mark points in freehand record
- Adds tie/off and pull-up on Resume during Pause state
- Improves stability of jump line drawings
- Segment counter added
- Create Simulation License button added
- Encrypted designs now recognized