



Baby Lock Aventura (Model BLMAV) Software Update Version 1.30

November 2021




Introduction

If the software version of your Aventura (Model BLMAV) is earlier than version 1.30, an update program is now available for download to improve its performance.

Version 1.30 update will provide the following changes:

1. The optional magnetic frame EMF180 can be recognized on the machine.

To confirm the software version of your BLMAV

2. Press the power switch to "|" to turn on your machine.
3. Press  (Settings key) to display the machine's settings screen.
4. Switch the settings screens by using  (Previous page key) or  (Next page key) to display the machine's program version.



5. If the "Version" shown in the screen is already "1.30" or later, it is not necessary to update your machine with this software version.





How to update your machine's software

You can use a **formatted** USB Flash drive to update your machine's software.


*** NOTE ***

- Do not turn off your machine while the machine is saving the update software to itself. If the machine's power is turned off while saving the update software, it may result in damage to the machine.
- Use a 4GB to 8 GB USB flash drive when updating the machine.
- Check that no data except for the update file_(FCBTE1A130.upf) is saved on the **formatted** USB Flash drive, before beginning update.

1. Insert the USB Flash drive into the USB port on the computer.
2. Copy only the update file to the USB Flash drive.
3. Safely remove the USB Flash drive from the USB port on the computer.
4. With the machine off, press and hold  “Presser Foot Lifter Button” while turning the main power on.




5. The following screen will appear on the LCD.







6. Insert the USB flash drive into the USB port on the machine.




7. Touch  (LOAD key).



8. The following screen appears on the LCD. Do not turn off your machine while the machine is saving the update software to itself.



9. When the following screen appears, updating is completed.



10. Remove the USB flash drive and turn the machine off and on again.
11. The machine's software has been updated to version 1.30.



Baby Lock Aventura (BLMAV) Update History

Version 1.26 update will provide the following changes:

1. The foot control communication with the machine has been optimized.

Version 1.22 update will provide the following changes:

1. Revised the wording of messages.

Version 1.21 update will provide the following changes:





1. Revised the wording of messages.

Version 1.11 update will provide the following changes:

1. Improved machine's functionality for the following feature.
-Reading the embroidery pattern from the original embroidery card.

NOTE: It is acceptable to attach USB reader/writer media to machine's USB port even though it is currently not stated within the instruction manual for the machine.


Version 1.10 update will provide the following changes:

1. Improved the software so that  (Size selection key) is not displayed.
2. Changed to return to Character/decorative stitch screen when pressing  (Back key) on Character/decorative stitch editing screen.
3. Improved the software so that the “Input Sensitivity” setting blinks when pressing any keys except for the  (Settings key) and  (Back key) on the operation panel.
4. Improved the font data No.06 and 07 to sew more attractively.
5. Change the movement speed of the embroidery frame when adjusting the embroidery position on Embroidery settings screen.
6. Improved the thumbnail displays for font No. 03 and 09.



Baby Lock Aventura (BLMAV) Update History

Version 1.09 update will provide the following changes:

1. Enhanced the texture of hand-look quilting stitch .
2. Improved the thumbnails of utility stitch selection screen.

Version 1.08 update will provide the following changes:

1. Improved the following features.
 - Embroidery Carriage Storage button function.
 - Running Stitch uniformity with frame pattern enlargement.

Version 1.07 update will provide the following changes:

1. Fixed the situation where the machine may not sew reinforcement stitches correctly when using the pivot function or the free motion sewing mode.
2. Fixed minor issues.