

# Baby Lock Accord (Model BLMCC) Software Update Version 1.07

April, 2018

#### Introduction


If the software version of your Accord (Model BLMCC) is earlier than version 1.07, an update program is now available for download to improve its performance.

## **Version 1.07 update will provide the following changes:**

1. Improved machine's functionality of foot controller with bobbin winding speed.

## To confirm the software version of your BLMCC

- 2. Press the power switch to "|" to turn on your machine.
- 3. Press (Settings key) to display the machine's settings screen.
- 4. Switch the settings screens by using (Previous page key) or (Next page key) to display the machine's program version.



5. If the "**Version**" shown in the screen is already "**1.07**" or later, it is not necessary to update your machine with the program on this page.

Copyright 2004-2018 Baby Lock USA Customer Support: 1-800-313-4110



### How to download the update program

- 1. Create a temporary folder (ex. C:\Temp) on your computer to save the update program file to be downloaded.
- 2. Click the "DOWNLOAD FILE" below.
- 3. Select the previously created temporary folder (ex. C:\Temp) where the downloaded file should be stored.
- 4. Download the file.

**Download FILE** (UPF File, size: 18.5 MB)

### How to update your machine's software

You can update the machine's software using a USB media.

Follow the procedure described in the instruction manual.

**Instruction PDF** (File size: 486 KB)

#### \* \* \* NOTE \* \* \*

- ➤ Do not turn off your machine while the machine is saving the update software to itself. If the machine's power is turned off while saving the update software, it may result in damage to the machine.
- ➤ When using USB Flash drive (USB Flash memory) to update the machine's software, check that no data except for the update file is saved on the USB Flash drive (USB Flash memory) being used before beginning update.



# **Baby Lock Accord (Model BLMCC) Update History**

- ➤ Version 1.06 update will provide the following changes:
  - 1. Minor improvement to touch panel function.
- ➤ Version 1.05 update will provide the following changes:
  - 1. Revised the wording of messages.
- **▶** Version 1.02 update will provide the following changes:
  - 1. Improved machine's functionality for the following feature.
    - Reading the embroidery pattern from the original embroidery card.

NOTE: It is acceptable to attach USB reader/writer media to machine's USB port even though it is currently not stated within the instruction manual for the machine.