

Regalia (BLRG20) Machine Update Version 4.77

We are continually making improvements to the Baby Lock Regalia machine.

Changes addressed in this release are as follows:

• Enhances the communication between machine and display to ensure all saved values load correctly when machine is powered on. This version of software slows communication with the tensioner to prevent incorrect readings being displayed.

Version 4.76:

 Corrects an issue where if the rear handle and display are not attached, attempts by the machine to communicate to that display will eventually cause the machine to ignore button presses, including the stop key. When this happens, the machine must be powered down to stop it.

Version 4.74:

• Fixed an issue with Pro-Stitcher turning off the machine lights when it boots up. The override switch state was not being saved in the machine.